## UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.

INVENTOR(S)

: 7,203,728 B2

Page 1 of 1

APPLICATION NO.: 10/714592

DATED

: April 10, 2007 : Jackson Lum

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In Column 8, Line 51

now reads "such that the 9 controller always"

should read --such that the I/O controller always--;

Signed and Sealed this

Eighteenth Day of September, 2007

JON W. DUDAS Director of the United States Patent and Trademark Office